

Office of the Sub Divisional Engineer Provincial Sub Division No. 1
PWD B & R Branch Hoshiarpur

To,

**The Principal,
Sarvhitkari Vidya Mandir Sr. Sec School,
Hoshiarpur**

No. 186

Dated: 02-07-2025

Subject: For issuance of Building Safety Certificate.

The building of above said school has been inspected by Junior Engineer Sh. **Anil Kumar** of this office. The building of the school found safe for the year **2025-26**, special attention be given in future to the following instructions:

- 1) There should not be gathered water on the roofs and surrounding the building.
- 2) If there is found any type of crack in any part of the building then the said spot should be vacated immediately and immediate repair should be done.
- 3) If you want to make construction except to the site plan attached then approval should be granted from the department.
- 4) Your institution/school will be responsible for safety of the building in all aspects. Fire extinguisher equipment must be in running condition.
- 5) This certificate is valid for the period of one year after issuance of this letter.

Encls/NIL

Sd/- xx
Sub Divisional Engineer,
Provincial Sub-Division No. 1
Hoshiarpur

Endorsement No.

Date

Copy of the above is being sent to Executive Engineer, Provincial Division PWD B&R Branch, Hoshiarpur for information. The requisite fee has been deposited by the school in A/c No. 311104000001502 dated: 24-06-2025 of your IDBI Bank.

Sd/-
Sub Divisional Engineer,
Provincial Sub-Division No. 1
Hoshiarpur



24 JUL 2025

Attested True Photocopy
Translation Copy of the
Document Produced

Ravinder Kumar
RAVINDER KUMAR
NOTARY PUBLIC
Hoshiarpur (Pb.)
(M) 62839-33086

ਦਫਤਰ: ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ ਨੰ: 1, ਲੋ: ਨਿ: ਵਿ: ਭ ਤੇ ਮ ਸਾਖਾ
ਹੁਸਿਆਰਪੁਰ

ਸੇਵਾ ਵਿਖੇ,

Principal,

Sarvhitkari Vidya Mandir Sr. Sen School,

Hoshiarpur.


ਨੰ: 186 ਮਿਤੀ: 21/7/2025

ਵਿਸ਼ਾ:- ਬਿਲਡਿੰਗ ਸੇਵਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕਰਨ ਸਬੰਧੀ।

ਉਪਰੋਕਤ ਸਕੂਲ ਦੀ ਇਮਾਰਤ ਦਾ ਨਿਰੀਖਣ ਇਸ ਦਫਤਰ ਦੇ ਜੂਨੀਅਰ ਇੰਜੀਨੀਅਰ ਸ੍ਰੀ ਅਨਿਲ ਕੁਮਾਰ ਵਲੋਂ ਕੀਤਾ ਗਿਆ। ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਸਾਲ 2025-26 ਲਈ ਸੁਰੱਖਿਅਤ ਪਾਈ ਗਈ ਹੈ ਅੱਗੇ ਤੋਂ ਹੇਠ ਲਿਖੀਆਂ ਹਦਾਇਤਾਂ ਵੱਲ ਵਿਸ਼ੇਸ਼ ਧਿਆਨ ਦਿੱਤਾ ਜਾਵੇ :-

1. ਬਿਲਡਿੰਗ ਦੀਆਂ ਫੁੱਤਾਂ ਅਤੇ ਆਲੇ ਦੁਆਲੇ ਪਾਣੀ ਨਾ ਖੜਾ ਹੋਣ ਦਿੱਤਾ ਜਾਵੇ।
2. ਜੇਕਰ ਇਮਾਰਤ ਵਿੱਚ ਕਿਸੇ ਕਿਸਮ ਦੀ ਤਰੇਡ ਵਗੈਰਾ ਆ ਜਾਂਦੀ ਹੈ ਤਾਂ ਉਸ ਜਗ੍ਹਾ ਨੂੰ ਤੁਰੰਤ ਖਾਲੀ ਕੀਤਾ ਜਾਵੇ ਅਤੇ ਉਸ ਦੀ ਰਿਪੇਅਰ ਤੁਰੰਤ ਕਰਵਾਈ ਜਾਵੇ।
3. ਨਾਲ ਨਕਸ਼ੇ ਤੋਂ ਇਲਾਵਾ ਜੇਕਰ ਆਪ ਵੱਲੋਂ ਕੋਈ ਵਾਧੂ ਉਸਾਰੀ ਕਰਨੀ ਹੋਵੇ ਤਾਂ ਉਸ ਦੀ ਮੰਨਜੂਰੀ ਇਸ ਮਹਿਕਮੇ ਪਾਸੋਂ ਲਈ ਜਾਵੇ।
4. ਬਿਲਡਿੰਗ ਦੀ ਹਰ ਪੱਖੋਂ ਸੇਵਟੀ ਦੀ ਸਾਰੀ ਜ਼ਿੰਮੇਵਾਰੀ ਆਪ ਦੀ ਸੰਸਥਾ/ਸਕੂਲ ਦੀ ਹੋਵੇਗੀ। ਅੱਗੇ ਬਥਾਉ ਯੰਤਰ ਚਾਲੂ ਹਾਲਤ ਵਿੱਚ ਹੋਣੇ ਚਾਹੀਦੇ ਹਨ।
4. ਇਹ ਸਰਟੀਫਿਕੇਟ ਦੀ ਮਿਆਦ ਦੀ ਮਿਤੀ 31/3/2026 ਹੈ।


ਨੱਥੀ/ਨਿੱਲ।


ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ ਨੰ: 1,
ਹੁਸਿਆਰਪੁਰ।
ਮਿਤੀ:

ਪਿ:ਅੰ:ਨੰ:

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਮੰਡਲ ਲੋ: ਨਿ: ਵਿ: ਭ ਤੇ ਮ ਸਾਖਾ ਹੁਸਿਆਰਪੁਰ ਜੀ ਨੂੰ ਸੂਚਨਾ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ। ਸਕੂਲ ਵਲੋਂ ਬਣਦੀ ਫੀਸ ਆਪ ਜੀ ਦੇ IDBI Bank ਦੇ ਖਾਤਾ ਨੰਬਰ 311104000001502 ਵਿੱਚ ਮਿਤੀ: 24/06/2025 ਨਾਲ ਜਮ੍ਹਾਂ ਕਰਵਾ ਲਈ ਹੈ ਜੀ।

ਨੱਥੀ/ਨਿੱਲ।


ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ ਨੰ: 1,
ਹੁਸਿਆਰਪੁਰ।